

FIG. 1

2/50




FIG. 2

METHOD FOR PROVIDING SENSORY FEEDBACK TO THE  
OPERATOR OF A PORTABLE MEASUREMENT MACHINE

Simon Raab et al  
Serial No. 10/642,427

3/50




FIG. 3

4/50




FIG. 3A

5/50




FIG. 4

FIG. 5

7/50




FIG. 6




FIG. 7



9/50





FIG. 8

10/50



11/50




FIG. 9A

12/50




FIG. 9E

FIG. 9D

FIG. 9C

FIG. 9B

FIG. 10

METHOD FOR PROVIDING SENSORY FEEDBACK TO THE  
OPERATOR OF A PORTABLE MEASUREMENT MACHINE

Simon Raab et al  
Serial No. 10/642,427

14/50




FIG. 11

15/50




FIG. 11A

16/50




FIG. 12



17/50




FIG. 12A

18/50




FIG. 13

19/50





FIG. 13A

METHOD FOR PROVIDING SENSORY FEEDBACK TO THE  
OPERATOR OF A PORTABLE MEASUREMENT MACHINE

Simon Raab et al  
Serial No. 10/642,427

20/50



*FIG 14*

21/50




FIG. 15

22/50




FIG. 15A

23/50




FIG. 16

METHOD FOR PROVIDING SENSORY FEEDBACK TO THE  
OPERATOR OF A PORTABLE MEASUREMENT MACHINE

Simon Raab et al  
Serial No. 10/642,427

24/50




FIG. 17




FIG. 18




FIG. 19



METHOD FOR PROVIDING SENSORY FEEDBACK TO THE  
OPERATOR OF A PORTABLE MEASUREMENT MACHINE

Simon Raab et al  
Serial No. 10/642,427

25/50




FIG. 20




FIG. 21




FIG. 22

26/50




FIG. 23A

METHOD FOR PROVIDING SENSORY FEEDBACK TO THE  
OPERATOR OF A PORTABLE MEASUREMENT MACHINE

Simon Raab et al  
Serial No. 10/642,427




FIG. 23B

28/50




FIG. 24

29/50




FIG. 24A

30/50




FIG. 25

31/50




FIG. 25A




FIG. 25B

32/50




FIG. 26



33/50




FIG. 26A

34/50




FIG. 26B

35/50




FIG. 27A

36/50





FIG. 27B

37/50



*FIG. 28*

38/50




FIG. 29

METHOD FOR PROVIDING SENSORY FEEDBACK TO THE  
OPERATOR OF A PORTABLE MEASUREMENT MACHINE

Simon Raab et al  
Serial No. 10/642,427




FIG. 29A




FIG. 29C







FIG. 29B

40/50





41/50




FIG. 31

42/50




FIG. 32

43/50




FIG. 33

44/50




FIG. 34

45/50




FIG. 35






FIG. 36

46/50



*FIG. 37*



*FIG. 38*

47/50




FIG. 40





FIG. 39





49/50




FIG. 42

50/50

